

# **Intel® 82580EB / 82580DB Gigabit Ethernet Controller Specification Update**

---

**LAN Access Division (LAD)**

**Revision 2.44  
May 2012**



## Legal

---

INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.

A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Contact your local Intel sales office or your distributor to obtain the latest specifications and before placing your product order.

Copies of documents which have an order number and are referenced in this document, or other Intel literature, may be obtained by calling 1-800-548-4725, or go to: <http://www.intel.com/design/literature.htm>.

Intel and Intel logo are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

\* Other names and brands may be claimed as the property of others.

Copyright © 2009-2012; Intel Corporation. All Rights Reserved.



## Revisions

---

| Date       | Revision | Description                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |
|------------|----------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 12/2009    | 1.0      | Initial public release                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                 |
| 01/14/2010 | 2.0      | Updated errata list for PRQ.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           |
| 02/03/2010 | 2.1      | Added spec. clarification: <ul style="list-style-type: none"> <li>1. EEPROM Required For Proper Operation of the 82580 Controller</li> </ul> Updated errata: <ul style="list-style-type: none"> <li>3. Possible System Hang During Enable/Disable When Connecting through nVidia* IO55 Slot</li> </ul>                                                                                                                                                                                                                                                                                                 |
| 03/01/2010 | 2.2      | Updated sections: <ul style="list-style-type: none"> <li>1.3 Identifying Marks</li> </ul>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |
| 06/25/2010 | 2.3      | Updated: <ul style="list-style-type: none"> <li>1.3 Identifying Marks. Added marking information for Engineering samples.</li> </ul> Updated or added errata: <ul style="list-style-type: none"> <li>6. LAN_DIS_N and AUX_PWR Pins Are Driven by the 82580 When Not Used for Strapping.</li> <li>7. MDIO: Com_MDIO and Destination Bits of MDICNFG Register Are Not Loaded Consistently from EEPROM.</li> <li>8. Dummy Function Present When All Ports are Disabled.</li> </ul>                                                                                                                        |
| 7/16/2010  | 2.31     | Added: <ul style="list-style-type: none"> <li>9. PCIe: Link Control 2 Register Contains Incorrect Read Values.</li> </ul> Updated: <ul style="list-style-type: none"> <li>1. TAG Not Reset by Power-on-reset Function. Status changed to Closed.</li> <li>5. PCIe Links at x1 Instead of x4 When Attached to Certain Chipset Ports.</li> </ul>                                                                                                                                                                                                                                                         |
| 8/20/2010  | 2.32     | Specification Clarification added: <ul style="list-style-type: none"> <li>3. Use of Wake on LAN Together with Manageability</li> </ul> Software Change added: <ul style="list-style-type: none"> <li>1. Update to PBA Number EEPROM Word Format.</li> </ul>                                                                                                                                                                                                                                                                                                                                            |
| 9/10/2010  | 2.33     | Specification Change updated: <ul style="list-style-type: none"> <li>1. Update to PBA Number EEPROM Word Format. Text updated to address confusion about new number format.</li> </ul>                                                                                                                                                                                                                                                                                                                                                                                                                 |
| 10/19/2010 | 2.34     | Software Clarification updated: <ul style="list-style-type: none"> <li>1. While In TCP Segmentation Offload, Each Buffer is Limited to 64 KB.</li> </ul>                                                                                                                                                                                                                                                                                                                                                                                                                                               |
| 1/6/2011   | 2.35     | Specification Clarification added: <ul style="list-style-type: none"> <li>5. SerDes: AN_TIMEOUT Only Works When Link Partner Idle.</li> </ul> Specification Changes added: <ul style="list-style-type: none"> <li>2. Updates to PXE/iSCSI EEPROM Words.</li> </ul> Errata added or text updated: <ul style="list-style-type: none"> <li>5. PCIe Links at x1 Instead of x4 When Attached to Certain Chipset Ports.</li> <li>10. I2C Data Out Hold Time Violation.</li> </ul> Software Clarification added: <ul style="list-style-type: none"> <li>2. EEPROM Checksum Not Set for LAN1, 2, 3.</li> </ul> |



| Date      | Revision | Description                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |
|-----------|----------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 2/25/2011 | 2.36     | Document title updated to correctly reflect brand strings.<br>Specification Clarification added: <ul style="list-style-type: none"><li>6. LED Modes Based on Link Speed Only work in Copper (Internal PHY) Mode.</li></ul> Specification Change updated: <ul style="list-style-type: none"><li>2. Updates to PXE/iSCSI EEPROM Words.</li></ul> Specification Change added: <ul style="list-style-type: none"><li>3. Update to Software Compatibility EEPROM Word 0x3.</li></ul> Errata added: <ul style="list-style-type: none"><li>11. SGMII: Counters Incorrectly Increment on Collision.</li><li>12. PCIe: Correctable Errors Reported When Using Rx L0s in a x1 Configuration.</li><li>13. TSYNCR: Auxiliary Timestamp from SDP is Unreliable.</li><li>14. PCIe: N_FTS Value is too Small When Common Clock Configuration is Zero.</li></ul> |
| 4/7/2011  | 2.37     | Tables updated. <ul style="list-style-type: none"><li>Table 1, Product and Device Identification.</li></ul>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |
| 7/20/2011 | 2.38     | Specification Clarifications added: <ul style="list-style-type: none"><li>7. PCIe: Completion Timeout Mechanism Compliance.</li><li>8. PCIe Timeout Interrupt</li></ul> Errata added: <ul style="list-style-type: none"><li>15. NC-SI: Command Interface Non-functional During PCIe Reset Due to Device Power Down State.</li><li>16. IEEE Std 802.3™-2008 Tx Distortion Marginality.</li></ul>                                                                                                                                                                                                                                                                                                                                                                                                                                                  |
| 8/15/2011 | 2.39     | Specification Clarifications updated: <ul style="list-style-type: none"><li>3. Use of Wake on LAN Together with Manageability. Driver-specific information added.</li><li>6. LED Modes Based on Link Speed Only work in Copper (Internal PHY) Mode. Error in problem statement corrected.</li></ul> Specification Change updated: <ul style="list-style-type: none"><li>4. Updated Definition of SW EEPROM Port Identification LED Blinking (Word 0x4). Updated section for datasheet provided.</li></ul> Software Clarification added: <ul style="list-style-type: none"><li>3. Serial Interfaces Programmed By Bit Banging.</li></ul>                                                                                                                                                                                                          |
| 8/24/2011 | 2.40     | Addresses production issue.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |
| 9/14/2011 | 2.41     | Specification changes: <ul style="list-style-type: none"><li>5. Minimum Value for Flow Control Receive Threshold Low. Added.</li></ul> Errata added: <ul style="list-style-type: none"><li>17. NC-SI: Get NC-SI Pass-through Statistics Response Format.</li></ul>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |
| 1/30/2012 | 2.43     | Specification Clarification added: <ul style="list-style-type: none"><li>9. Padding on Transmitted SCTP Packets.</li></ul>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       |
| 5/2/2012  | 2.44     | Errata added: <ul style="list-style-type: none"><li>18. PCIe Reset Causes FW Reset When Ports Are Disabled.</li></ul>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |



## 1.1 Introduction

This document is an update to the product datasheet. It is intended for use by system manufacturers and software developers. All product documents are subject to frequent revision. Be sure you have the latest information before finalizing your design.

References to PCIe\* in this document refer to PCIe v2.0 (5Gbps).

## 1.2 Product and Device Identification

**Table 1. Product and Device Identification**

| MM#    | Stepping | Top Marking | Spec # | Intel SPEED iPN | Status & Media    | Description          |
|--------|----------|-------------|--------|-----------------|-------------------|----------------------|
| 905781 | A1       | NH82580EB   | S LH5P | E69716-003      | Production, T&R   | 1 Gbs, 4-port        |
| 905782 | A1       | NH82580EB   | S LH5Q | E69716-004      | Production, Tray  |                      |
| 905783 | A1       | NH82580EK   | S LH5R | E82069-002      | Production, T&R   | 1 Gbs 4-port SERDES  |
| 905784 | A1       | NH82580EK   | S LH5S | E82069-003      | Production, Tray  |                      |
| 905785 | A1       | NH82580DB   | S LH5T | E82070-002      | Production, T&R   | 1 Gbs, 2-port        |
| 905786 | A1       | NH82580DB   | S LH5U | E82070-003      | Production, Tray  |                      |
| 904983 | A1       | NH82580EB   | Q MQR  | E69716-002      | Engineering, Tray | 1 Gbs, 4 port        |
| 907335 | A1       | NH82580EK   | Q MQT  | E82069-001      | Engineering, Tray | 1 Gbs, 4-port SERDES |
| 907334 | A1       | NH82580DB   | Q MQS  | E82070-001      | Engineering, Tray | 1 Gbs, 2-port        |
| 903315 | A0       | NH82580EB   | Q LSY  | E69716-001      | Engineering, Tray | 1 Gbs, 4-port        |



### 1.3 Identifying Marks




Figure 1. Sample Component Diagram Illustrating Identifying Marks

Refer to Figure 1:

|        |                                                                                   |
|--------|-----------------------------------------------------------------------------------|
| Line 1 | "intel"                                                                           |
| Line 2 | Marketing Name                                                                    |
| Line 3 | Fab Lot Number "XXXXXXXX" (Wafer Lot no. concatenated with Assembler vendor code) |
| Line 4 | Assembly Date Code YYWW; Engineering samples have additional Intel data.          |
| Line 5 | Copyright line; includes two number date code and the Pb-free mark (e1)           |
| Line 6 | Country of Origin                                                                 |

### 1.4 Nomenclature Used In This Document

This document uses specific terms, codes, and abbreviations to describe changes, errata, sightings and/or clarifications that apply to a specific silicon stepping. See Table 2 for a description.

Table 2. Nomenclature

| Name                  | Description                                                                                                                                                                                                                                                 |
|-----------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Specification Changes | Modifications to the current published specifications. These changes will be incorporated in the next release of the specifications.                                                                                                                        |
| Errata                | Design defects or errors. Errata may cause device behavior to deviate from published specifications. Hardware and software designed to be used with any given stepping must assume that all errata documented for that stepping are present on all devices. |



**Table 2. Nomenclature**

|                              |                                                                                                                                                                                                                                                                                                                            |
|------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Sightings                    | Observed issues that are believed to be errata, but have not been completely confirmed or root caused. The intention of documenting sightings is to proactively inform users of behaviors or issues that have been observed. Sightings may evolve to errata or may be removed as non-issues after investigation completes. |
| Specification Clarifications | Greater detail or further highlights concerning a specification's impact to a complex design situation. These clarifications will be incorporated in the next release of the specifications.                                                                                                                               |
| Software Clarifications      | Applies to Intel drivers, EEPROM loads.                                                                                                                                                                                                                                                                                    |
| Documentation Corrections    | Errors, or omissions in current published specifications. These changes are incorporated in the next release of the applicable document and then dropped from the specupdate. You may also check for changes in the revision history of specific documents.                                                                |
| A1, B1, etc.                 | Stepping to which the status applies.                                                                                                                                                                                                                                                                                      |
| Doc                          | Document change or update that will be implemented.                                                                                                                                                                                                                                                                        |
| Fix                          | This erratum is intended to be fixed in a future stepping of the component.                                                                                                                                                                                                                                                |
| Fixed                        | This erratum has been fixed.                                                                                                                                                                                                                                                                                               |
| EEPROM/NVM Fix               | This indicates the Errata was in the EEPROM/NVM and is fixed in an updated version.                                                                                                                                                                                                                                        |
| NoFix                        | There are no plans to fix this erratum.                                                                                                                                                                                                                                                                                    |
| Eval                         | Plans to fix this erratum are under evaluation.                                                                                                                                                                                                                                                                            |
| Red Change Bar/<br>or Bold   | This Item is either new or modified from the previous version of the document.                                                                                                                                                                                                                                             |

## 1.5 Sightings, Clarifications, Changes, Errata, Software Clarifications

See Section 1.4 above for an explanation of terms, codes, and abbreviations.

**Table 3. Summary of Sightings, Clarifications, Changes, Errata, Software Clarifications**

| Sightings                                                                      | Status |
|--------------------------------------------------------------------------------|--------|
| 1. None.                                                                       | N/A    |
| Specification Clarifications                                                   | Status |
| 1. EEPROM Required For Proper Operation of the 82580 Controller                | N/A    |
| 2. AC JTAG Junction Temperature Limit                                          | N/A    |
| 3. Use of Wake on LAN Together with Manageability                              | N/A    |
| 4. SMBus: Illegal STOP Condition                                               | N/A    |
| 5. SerDes: AN_TIMEOUT Only Works When Link Partner Idle                        | N/A    |
| 6. LED Modes Based on Link Speed Only work in Copper (Internal PHY) Mode       | N/A    |
| 7. PCIe: Completion Timeout Mechanism Compliance                               | N/A    |
| 8. PCIe Timeout Interrupt                                                      | N/A    |
| 9. Padding on Transmitted SCTP Packets                                         | N/A    |
| Specification Changes                                                          | Status |
| 1. Update to PBA Number EEPROM Word Format                                     | N/A    |
| 2. Updates to PXE/iSCSI EEPROM Words                                           | N/A    |
| 3. Update to Software Compatibility EEPROM Word 0x3                            | N/A    |
| 4. Updated Definition of SW EEPROM Port Identification LED Blinking (Word 0x4) | N/A    |

**Table 3. Summary of Sightings, Clarifications, Changes, Errata, Software Clarifications**

|                                                                                                    |                 |
|----------------------------------------------------------------------------------------------------|-----------------|
| 5. Minimum Value for Flow Control Receive Threshold Low                                            | N/A             |
|                                                                                                    |                 |
| <b>Errata</b>                                                                                      |                 |
| 1. TAG Not Reset by Power-on-reset Function                                                        | Closed          |
| 2. MNG Reset Clears Resource Grant With No Feedback                                                | A1 NoFix        |
| 3. Possible System Hang During Enable/Disable When Connecting through nVidia* IO55 Slot            | A1 NoFix        |
| 4. SMBus: EEPROM Not Written On ARP If the EEPROM Semaphore Is Taken by SW                         | A1 NoFix        |
| 5. PCIe Links at x1 Instead of x4 When Attached to Certain Chipset Ports                           | A1 NoFix        |
| 6. LAN_DIS_N and AUX_PWR Pins Are Driven by the 82580 When Not Used for Strapping                  | A1 NoFix        |
| 7. MDIO: Com_MDIO and Destination Bits of MDICNFG Register Are Not Loaded Consistently from EEPROM | A1 NoFix        |
| 8. Dummy Function Present When All Ports are Disabled                                              | A1 NoFix        |
| 9. PCIe: Link Control 2 Register Contains Incorrect Read Values                                    | A1 NoFix        |
| 10. I2C Data Out Hold Time Violation                                                               | A1 NoFix        |
| 11. SGMII: Counters Incorrectly Increment on Collision                                             | A1 NoFix        |
| 12. PCIe: Correctable Errors Reported When Using Rx L0s in a x1 Configuration                      | A1 NoFix        |
| 13. TSYNC: Auxiliary Timestamp from SDP is Unreliable                                              | A1 NoFix        |
| 14. PCIe: N_FTS Value is too Small When Common Clock Configuration is Zero                         | A1 NoFix        |
| 15. NC-SI: Command Interface Non-functional During PCIe Reset Due to Device Power Down State       | A1 NoFix        |
| 16. IEEE Std 802.3™-2008 Tx Distortion Marginality                                                 | A1 NoFix        |
| 17. NC-SI: Get NC-SI Pass-through Statistics Response Format                                       | A1 NoFix        |
| 18. PCIe Reset Causes FW Reset When Ports Are Disabled                                             | Fixed in EEPROM |
| <b>Software Clarifications</b>                                                                     |                 |
| 1. While In TCP Segmentation Offload, Each Buffer is Limited to 64 KB                              | N/A             |
| 2. EEPROM Checksum Not Set for LAN1, 2, 3                                                          | N/A             |
| 3. Serial Interfaces Programmed By Bit Banging                                                     | N/A             |

### 1.5.1 Sightings

1. None.

### 1.5.2 Specification Clarifications

#### 1. EEPROM Required For Proper Operation of the 82580 Controller

**Clarification:** Problems identified in the PCIe logic were resolved by implementing workarounds in EEPROM. Without these workarounds, the PCIe bus may not properly configure and the possibility exists that the controller will not negotiate a PCIe connection. This leaves the 82580 inaccessible.

**Workaround:** Use an EEPROM with the workarounds (v3.22 or greater) to ensure proper device configuration.





## 2. AC JTAG Junction Temperature Limit

Specification: IEEE 1149.6: A Boundary-Scan Standard for Advanced Digital Networks

Clarification: AC JTAG (IEEE 1149.6) is supported only up to a junction temperature of 70°C.

Workaround: None. This is a design parameter for the hardware.

## 3. Use of Wake on LAN Together with Manageability

Clarification: The Wakeup Filter Control Register (WUFC) contains the NoTCO bit, which affects the behavior of the wakeup functionality when manageability is in use. Note that if manageability is not enabled, the value of NoTCO has no effect.

When NoTCO contains the hardware default value of 0b, any received packet that matches the wakeup filters will wake the system. This could cause unintended wakeups in certain situations. For example, if Directed Exact Wakeup is used and the manageability shares the host's MAC address, IPMI packets that are intended for the BMC wakes the system, which might not be the intended behavior.

When NoTCO is set to 1b, any packet that passes the manageability filter, even if it also is copied to the host, is excluded from the wakeup logic. This solves the previous problem since IPMI packets do not wake the system. However, with NoTCO=1b, broadcast packets, including broadcast magic packets, do not wake the system since they pass the manageability filters and are therefore excluded.

| Effects of NoTCO Settings WoL | NoTCO | Shared MAC Address | Unicast Packet                                                      | Broadcast Packet |
|-------------------------------|-------|--------------------|---------------------------------------------------------------------|------------------|
| Magic Packet                  | 0b    | -                  | OK                                                                  | OK               |
| Magic Packet                  | 1b    | Y                  | No wake                                                             | No wake          |
| Magic Packet                  | 1b    | N                  | OK                                                                  | No wake          |
| Directed Exact                | 0b    | Y                  | Wake even if MNG packet. No way to talk to BMC without waking host. | N/A              |
| Directed Exact                | 0b    | N                  | OK                                                                  | N/A              |
| Directed Exact                | 1b    | -                  | OK                                                                  | N/A              |

The Intel Windows\* drivers set NoTCO by default.

If this is not not desired behavior, the EnableWakeOnManagementOnTCO registry entry can be used to change this setting starting with Intel LAN driver SW release 15.7. Setting this registry entry to 1b causes the driver to program NoTCO to 0b. A tool to modify the registry entry can be provided.

Contact your Intel representative for access.

## 4. SMBus: Illegal STOP Condition

Clarification: It is important to prevent illegal STOP conditions on the SMBus interface, even when resetting the MC.



Specifically, a STOP condition should never be generated by the MC during the high clock phase of an ACK cycle while reading packet data from the 82580 as part of a Receive TCO LAN packet transaction.

If this situation occurs, the 82580 replies with a NACK to all future commands until a power cycle. As a result, the SMBus interface becomes inoperable.

Workaround: Ensure that this illegal sequence does not occur, even during MC reset.

## 5. SerDes: AN\_TIMEOUT Only Works When Link Partner Idle

Clarification: The auto-negotiation timeout mechanism (PCS\_LCTL.AN\_TIMEOUT\_EN) only works if the SerDes partner is sending idle code groups continuously for the duration of the timeout period, which is the usual case.

However, if the partner is transmitting packets, an auto-negotiation timeout will not occur since auto-negotiation is restarted at the beginning of each packet. If the partner has an application that indefinitely transmits data despite the lack of any response, it is possible that a link will not be established.

Workaround: If this is a concern, the auto-negotiation timeout mechanism may be considered unreliable and an additional software mechanism could be used to disable auto-negotiation if sync is maintained without a link being established (PCS\_LSTS.SYNC\_OK=1b and PCS\_LSTS.LINK\_OK=0b) for an extended period of time.

## 6. LED Modes Based on Link Speed Only work in Copper (Internal PHY) Mode

Clarification: LED modes based on LINK speed work only in copper mode, not in SerDes/SGMII modes. This includes the modes LINK\_10/1000, LINK\_100/1000, LINK\_10, LINK\_100, LINK\_1000 and COLLISION.

Designs using SerDes and SGMII modes requiring a Link-up indication should use LINK\_UP or LINK/ACTIVITY LED modes. Using these modes results in no issues in using the LEDs to properly indicate the link is up.

## 7. PCIe: Completion Timeout Mechanism Compliance

Clarification: The 82580 Completion Timeout Value[3:0] must be properly set by the system BIOS in the 82580 PCIe Configuration Space Device Control 2 register (0xC8; W). Failure to do so can cause unexpected completion timeouts.

The 82580 complies with the PCIe 2.0 specification for the completion timeout mechanism and programmable timeout values. The PCIe 2.0 specification provides programmable timeout ranges between 50us to 64s with a default time range of 50us - 50ms. The 82580 defaults to a range of 16ms - 32ms.

Workaround: The completion timeout value must be programmed correctly in PCIe configuration space (in Device Control 2 register); the value must be set above the expected maximum latency for completions in the system in which the 82580 is installed. This ensures that the 82580 receives the completions for the requests it sends out, avoiding a completion timeout scenario. Failure to properly set the completion timeout value can result in the device timing out prior to a completion returning.

## 8. PCIe Timeout Interrupt

Clarification: The PCIe Timeout Exception (TO) bit in the PCIe Interrupt Cause (PICAUSE) register is set when a timeout occurs on an access to the address space of this port. This includes accesses initiated by the EEPROM auto-load function and manageability firmware, in addition to accesses from the PCIe interface.



This interrupt bit does not necessarily indicate a problem with a PCIe transaction and further analysis would be required to determine the source of problem.

## 9. Padding on Transmitted SCTP Packets

Clarification: When using the 82580EB/DB to offload the CRC calculation for transmitted SCTP packets, software should not add Ethernet padding bytes to short packets (less than 64 bytes). Instead, the TCTL.PSP bit should be set so that the 82580EB/DB pads the packets after performing the CRC calculation.

## 1.5.3 Specification Changes

### 1. Update to PBA Number EEPROM Word Format

Change: PBA Number Module — Word 0x8-0x9

The nine-digit Printed Board Assembly (PBA) number used for Intel manufactured Network Interface Cards (NICs) is stored in EEPROM.

Through the course of hardware ECOs, the suffix field is incremented. The purpose of this information is to enable customer support (or any user) to identify the revision level of a product.

Network driver software should not rely on this field to identify the product or its capabilities.

PBA numbers have exceeded the length that can be stored as HEX values in two words. For newer NICs, the high word in the PBA Number Module is a flag (0xFAFA) indicating that the actual PBA is stored in a separate PBA block. The low word is a pointer to the starting word of the PBA block.

The following shows the format of the PBA Number Module field for new products.

| PBA Number | Word 0x8 | Word 0x9             |
|------------|----------|----------------------|
| G23456-003 | FAFA     | Pointer to PBA Block |

The following provides the format of the PBA block; pointed to by word 0x9 above:

| Word Offset | Description                                       |
|-------------|---------------------------------------------------|
| 0x0         | Length in words of the PBA Block (default is 0x6) |
| 0x1 ... 0x5 | PBA Number stored in hexadecimal ASCII values.    |

The new PBA block contains the complete PBA number and includes the dash and the first digit of the 3-digit suffix which were not included previously. Each digit is represented by its hexadecimal-ASCII values.

The following shows an example PBA number (in the new style):

| PBA Number | Word Offset 0 | Word Offset 1 | Word Offset 2 | Word Offset 3 | Word Offset 4 | Word Offset 5 |
|------------|---------------|---------------|---------------|---------------|---------------|---------------|
|------------|---------------|---------------|---------------|---------------|---------------|---------------|



|            |                   |      |      |      |      |      |
|------------|-------------------|------|------|------|------|------|
| G23456-003 | 0006              | 4732 | 3334 | 3536 | 2D30 | 3033 |
|            | Specifies 6 words | G2   | 34   | 56   | -0   | 03   |

Older NICs have PBA numbers starting with [A,B,C,D,E] and are stored directly in words 0x8-0x9. The dash in the PBA number is not stored; nor is the first digit of the 3-digit suffix (the first digit is always 0b for older products).

The following example shows a PBA number stored in the PBA Number Module field (in the old style):

| PBA Number | Byte 1 | Byte 2 | Byte 3 | Byte 4 |
|------------|--------|--------|--------|--------|
| E23456-003 | E2     | 34     | 56     | 03     |

## 2. Updates to PXE/iSCSI EEPROM Words

Change: Word 0x30, 34, 38, 3A are now defined as follows:

| Bit(s) | Value                                                                                                       | Port Status     | CLP (Combo) Executes | iSCSI Boot Option ROM CTRL-D Menu                                                         | FCoE Boot Option ROM CTRL-D Menu                                        |
|--------|-------------------------------------------------------------------------------------------------------------|-----------------|----------------------|-------------------------------------------------------------------------------------------|-------------------------------------------------------------------------|
| 15:6   | Same as before.                                                                                             |                 |                      |                                                                                           |                                                                         |
| 5      | Bit 5, formerly used to indicate iSCSI enable / disable, is no longer valid and is not checked by software. |                 |                      |                                                                                           |                                                                         |
| 4:3    | Same as before.                                                                                             |                 |                      |                                                                                           |                                                                         |
| 2:0    | 101-111                                                                                                     | Reserved        |                      |                                                                                           |                                                                         |
|        | 100                                                                                                         | FCoE            | FCOE                 | Displays port as FCoE. Allows changing port to Boot Disabled, iSCSI Primary or Secondary. | Displays port as FCoE. Allows changing to Boot Disabled.                |
|        | 011                                                                                                         | iSCSI Secondary | iSCSI                | Displays port as iSCSI Secondary. Allows changing to Boot Disabled, iSCSI Primary.        | Displays port as iSCSI. Allows changing to Boot Disabled, FCoE Enabled. |
|        | 010                                                                                                         | iSCSI Primary   | iSCSI                | Displays port as iSCSI Primary. Allows changing to Boot Disabled, iSCSI Secondary.        | Displays port as iSCSI. Allows changing to Boot Disabled, FCoE Enabled. |
|        | 001                                                                                                         | Boot Disabled   | NONE                 | Displays port as Disabled. Allows changing to iSCSI Primary/Secondary.                    | Displays port as Disabled. Allows changing to FCoE enabled.             |
|        | 000                                                                                                         | PXE             | PXE                  | Displays port as PXE. Allows changing to Boot Disabled, iSCSI Primary or Secondary.       | Displays port as PXE. Allows changing to Boot Disabled, FCoE Enabled.   |



### 3. Update to Software Compatibility EEPROM Word 0x3

Change: To Software Compatibility EEPROM Word 0x3:

| Bit   | Name                   | Default | Description                                                                                                                                                                                                            |
|-------|------------------------|---------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 15    | Checksum Flag/Reserved | 0       | 0b: Only the checksum for LAN0 is valid<br>1b: All 4 LAN checksum are valid.                                                                                                                                           |
| 14:13 | Reserved               | 0       | Reserved                                                                                                                                                                                                               |
| 12    | Reserved               | 0       | Reserved                                                                                                                                                                                                               |
| 11    | LOM                    | 0       | Indicates whether dedicated flash for the option ROM is attached to LAN silicon. Used by option ROM update applications (DMIX).<br>0b: NIC (A dedicated flash is attached)<br>1b: LOM (No dedicated flash is attached) |
| 10    | Reserved               | 0       | Reserved                                                                                                                                                                                                               |
| 9     | Client                 | 0       | Client/Not a Client NIC<br>0b = Server.<br>1b = Client.<br>This bit is used by DMIX to verify the NIC is server or client. A team is required to have server NIC or LOM.                                               |
| 8     | Reserved               | 0       | Reserved.                                                                                                                                                                                                              |
| 7:5   | Reserved               | 0       | Reserved                                                                                                                                                                                                               |
| 4     | Reserved               | 0       | Reserved                                                                                                                                                                                                               |
| 3     | Reserved               | 0       | Reserved                                                                                                                                                                                                               |
| 2     | Reserved               | 0       | Reserved                                                                                                                                                                                                               |
| 1:0   | Reserved               | 0       | Reserved                                                                                                                                                                                                               |

### 4. Updated Definition of SW EEPROM Port Identification LED Blinking (Word 0x4)

Change Port Identification LED blinking (Word 0x04)

Driver software provides a method to identify an external port on a system through a command that causes the LEDs to blink. Based on the setting in word 0x4, the LED drivers should blink between STATE1 and STATE2 when a port identification command is issued.



When word 0x4 is equal to 0xFFFF or 0x0000, the blinking behavior reverts to a default.

| Bit   | Description                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |
|-------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 15:12 | Control for LED 3<br>0000b or 1111b: Default LED Blinking operation is used.<br>0001b = Default in STATE1 + Default in STATE2.<br>0010b = Default in STATE1 + LED is ON in STATE2.<br>0011b = Default in STATE1 + LED is OFF in STATE2.<br>0100b = LED is ON in STATE1 + Default in STATE2.<br>0101b = LED is ON in STATE1 + LED is ON in STATE2.<br>0110b = LED is ON in STATE1 + LED is OFF in STATE2.<br>0111b = LED is OFF in STATE1 + Default in STATE2.<br>1000b = LED is OFF in STATE1 + LED is ON in STATE2.<br>1001b = LED is OFF in STATE1 + LED is OFF in STATE2.<br>All other values are Reserved. |
| 11:8  | Control for LED 2 – same encoding as for LED 3.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                |
| 7:4   | Control for LED 1 – same encoding as for LED 3.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                |
| 3:0   | Control for LED 0 – same encoding as for LED 3.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                |

## 5. Minimum Value for Flow Control Receive Threshold Low

Change: If FCRTL0.XONE is 1, the minimum value allowed in FCRTL0.RTL is 3 (48 bytes).

### 1.5.4 Errata

#### 1. TAG Not Reset by Power-on-reset Function

Note: Not applicable to current products.

Status: Closed

#### 2. MNG Reset Clears Resource Grant With No Feedback

Problem: When accessing the EEPROM (via EEC register) or FLASH (via FLA register), grants may be lost due to deadlock or FW reset. Software will not be notified of the lost grant. A driver in the middle of a bit bang may renew the request and receive the grant without knowing that it is actually starting a new transaction.

Implications:

1. FLA/EEC bit banging transactions may fail.
2. Long transactions may turn into different transactions than expected.

Workaround:

1. SW should not execute bit bang sequences longer than one word at a time.



2. When SW reads the EEC/FLA, it should make sure that it still has the request and grant; if not it should renew it and re-start the transaction (this does not cover all cases but reduces the possibility of a problem).

Status: A1 NoFix

### 3. Possible System Hang During Enable/Disable When Connecting through nVidia\* IO55 Slot

Problem: Once the link is up, when the 82580 tries to connect with the nVidia IO55 chipset, the following may occur:

- The Link layer tries to train but not all lanes work.
- The 82580EB/DB tries retraining with fewer lanes; but during retraining may loop.
- The system hangs.

Implication: The 82580 cannot reliably connect using this configuration.

Workaround: Connecting to a different port on the system.

Status: A1 NoFix

### 4. SMBus: EEPROM Not Written On ARP If the EEPROM Semaphore Is Taken by SW

Problem: If an SMBus ARP address is stored at the same time the EEPROM is locked by SW, the address is not be saved.

Implication : Wrong SMBus address after firmware reset.

Workaround: Set the SMBus address in the EEPROM (not through ARP).

Status: A1 NoFix

### 5. PCIe Links at x1 Instead of x4 When Attached to Certain Chipset Ports

Problem: When the 82580 is connected to certain PCIe x4 ports, the PCIe link is x1 instead of x4. The affected ports on Intel devices have a Device ID of 0x2690. These ports can be found on:

- 6311ESB2/6321ESB2 I/O Controller Hub
- INTEL 3100 SCH Port B

Implications: If the PCIe link is x1, the bandwidth is limited and might not be sufficient for all device ports, resulting in a performance bottleneck.

Workaround: Do not attach the 82580 to this chipset port. If such a connection cannot be avoided, please contact your Intel representative for assistance.

Status: A1 NoFix

### 6. LAN\_DIS\_N and AUX\_PWR Pins Are Driven by the 82580 When Not Used for Strapping

Problem: At other times, these pins become outputs and are driven low.



Implication If these pins are driven high from another device, there could be high current draw.

If the external pull-up resistor used on these pins is not strong enough, the wrong value could be sampled at the beginning of the PCIe reset.

Workaround When driving the LANx\_DIS\_N and/or AUX\_PWR pins from another device, use a series resistor between the devices to reduce the current.

For both external pull-up resistors and series resistors, ensure that the resistor is strong enough to pull up the pin within 40 ns. Assuming relatively short traces between the 82580 and the resistor, a 3.3 K ohm resistor should work well. Larger resistance values should not be used.

Status: A1 NoFix

## 7. MDIO: Com\_MDIO and Destination Bits of MDICNFG Register Are Not Loaded Consistently from EEPROM

Problem: The Com\_MDIO (bit 30) and Destination (bit 31) bits of the MDICNFG register (0x0E04) are not loaded consistently from the EEPROM. In some cases, the hardware default value of 0b is used instead.

Implication Software that relies on the EEPROM-loaded value might not be able to initialize an external PHY. When not using an external PHY, there is no issue.

Workaround Software should assume that the initial values of these bits are undefined and should program them before attempting to initialize an external PHY. The EEPROM bits can be used to determine the intended settings.

Status: A1 NoFix

## 8. Dummy Function Present When All Ports are Disabled

Problem: When all ports are disabled, either by strapping pins or by EEPROM settings, no PCIe functions should be present. However, if the Dummy Function Enable EEPROM bit (word 0x1B, bit 14) is set to 1b, Function 0 becomes a dummy function even if all ports are disabled.

Implication Even with all ports disabled, Function 0 appears in the system PCIe enumeration with a Device ID of 0x10A6, indicating a dummy function. This should not have any effect on the system.

Workaround N/A

Status: A1 NoFix

## 9. PCIe: Link Control 2 Register Contains Incorrect Read Values

Problem: The Target Link Speed and Transmit Margin fields of the Link Control 2 Register in the PCIe configuration space are described as follows in the PCIe specification:

“For a Multi-Function device associated with an Upstream Port, the field in Function 0 is of type RWS, and only Function 0 controls the component’s Link behavior. In all other Functions of that device, this field is of type RsvdP.”

This means that when reading the Link Control 2 Register on functions other than Function 0, these fields should be 0b. Instead, the 82580 returns the value written to Function 0, behavior which differs from the specification.





Implication: No functional implication since these fields are defined as reserved and ignored by software.

Workaround: N/A

Status: A1 NoFix

## 10. I<sup>2</sup>C Data Out Hold Time Violation

Problem: The 82580 should provide a data out hold time of 50 ns on the SFPx\_I2C\_DATA pins. The actual hold time is about 16 ns.

Implication: Timing specification violation. There have been no reports of failures resulting from this timing. Note that the data input hold time required is zero, so the provided output hold time should be more than enough as long as the I<sup>2</sup>C CLK and DATA signals are reasonably matched on the board.

Workaround: N/A

Status: A1 NoFix

## 11. SGMII: Counters Incorrectly Increment on Collision

Problem: In SGMII mode/half duplex, the statistics counters listed below incorrectly increment when a collision occurs:

| Name    | Definition            | Location |
|---------|-----------------------|----------|
| RLEC    | Length error counter  | 0X4040   |
| CRCERRS | CRC error counter     | 0x4000   |
| RFC     | receive frame counter | 0x40A8   |

Implication: Error counters may not be accurate.

Workaround: None.

Status: A1 NoFix

## 12. PCIe: Correctable Errors Reported When Using Rx L0s in a x1 Configuration

Problem: When using Rx L0s in an x1 configuration, the 82580 reports receiver errors at a rate of more than one per minute on some platforms.

Implication: Correctable errors are reported at a higher rate than can be explained by random bit errors. These errors should be ignored by the system.

Workaround: None.

Status: A1 NoFix

## 13. TSYNC: Auxiliary Timestamp from SDP is Unreliable

Problem: The SDP inputs to the timestamp logic are not properly synchronized. As a result, both the Auxiliary Timestamp Register values and the Auxiliary Timestamp Taken bits in TSAUXC are sometimes loaded incorrectly.

Implication: The auxiliary timestamp feature should be considered unreliable.



**Workaround:** For applications that use the auxiliary timestamp feature to synchronize to an external clock, it might be acceptable to drop some of the samples. For such applications, software can filter out many of the incorrect timestamp values by comparing them to an approximate expected timestamp and discarding unreasonable values.

In addition, the following method can be used to filter out incorrect values:

- Connect the input signal to two SDP inputs for the same port.
- Using the TSSDP register, assign one of the SDP inputs to AUX0 and the other SDP input to AUX1.
- When reading the TSAUXC register to check for new samples, check that both AUTTO and AUTT1 are set. Otherwise, discard the sample.
- Read both the AUX0 and AUX1 timestamp values and compare the values. Discard the values if they differ by more than the sampling uncertainty -- 8 ns if the SDP inputs are balanced externally or slightly higher if the external trace lengths differ significantly.

Using this method, along with a SW filter for expected values, almost all errors can be filtered out, with the remaining samples having a very high probability of being correct.

When using Port 0, the following combinations of SDP connections to AUX0 and AUX1 allow the above method to filter out all errors.

| <b>AUX0<br/>Connection</b> | <b>AUX1<br/>Connection</b> |
|----------------------------|----------------------------|
| SDP0                       | SDP1                       |
| SDP0                       | SDP3                       |
| SDP1                       | SDP0                       |
| SDP1                       | SDP2                       |
| SDP2                       | SDP0                       |
| SDP2                       | SDP1                       |
| SDP2                       | SDP3                       |
| SDP3                       | SDP2                       |

**Status:** A1 NoFix

#### 14. PCIe: N\_FTS Value is too Small When Common Clock Configuration is Zero

**Problem:** When the Common Clock Configuration bit in the Link Control Register is 0b, the value of N\_FTS advertised by the 82580 is taken from internal configuration registers, with separate values used for Gen1 and Gen2 speeds. The hardware default values are too small to guarantee a clean exit from L0s in all cases.

As a result, link recovery procedures might be performed and Correctable Errors might be reported: Bad TLP, Bad DLLP, and Replay Timer Timeout.

Note that even on platforms where the Common Clock Configuration is set to 1b, this bit is cleared by Hot Reset or D3->D0 transitions, and the previous situation can still occur until the configuration space programming has been restored.

**Implications:** The Correctable Errors can generally be ignored. The link recovery procedures and replayed packets result in a small reduction of effective bandwidth on the PCIe link.

However, in certain circumstances on some platforms, the repeated loss of packets can lead to a Completion Timeout error, which might cause the application and/or the system to stop working.

**Workaround:** Disable L0s on the upstream device.

OR



Disable L0s on the upstream device before putting the 82580 in Hot Reset or D3 states.

OR

Upgrade EEPROM image. Fix in EEPROM version 3.29. Contact your Intel representative to obtain updated EEPROM images.

Status: A1 NoFix

## 15. NC-SI: Command Interface Non-functional During PCIe Reset Due to Device Power Down State

**Problem:** When the conditions for the Device Power Down State exist during power-up and NC-SI manageability is enabled, the MNG firmware is unable to respond to commands during PCIe reset.

This occurs when all the following are true:

- Power Down Enable EEPROM bit (word 0x1E bit 15) is set.
- PHY Power Down Enable EEPROM bit (offset 0x0F bit 6) is set for all ports using a copper link.
- SerDes Low Power Enable EEPROM bit (offset 0x0F bit 2) is set for all ports using a SerDes link.
- APM Enable EEPROM bit (offset 0x24 bit 10) is clear for all ports.

**Implication:** The NC-SI interface is non-functional during PCIe reset. Once PCIe reset has been negated and a Clear Initial State command has been executed, the interface functions as expected even if PCIe reset is asserted again.

**Workaround:** If the DEV\_OFF\_N input pin is not being used and if manageability is enabled, the Power Down Enable EEPROM bit (word 0x1E, bit 15) should be 0.

If the DEV\_OFF\_N input pin needs to be functional in the design, do not use the combination of EEPROM settings described above that causes this condition. For example, clear the PHY Power Down Enable bit on at least one port if using an NC-SI image.

Status: A1 NoFix

## 16. IEEE Std 802.3™-2008 Tx Distortion Marginality

**Problem:** The 82580 might not meet the IEEE Std 802.3™-2008 specification (40.6.1.2.4) that states that the Tx Distortion must meet the following criteria. "A PHY is considered to pass this test if the peak distortion is below 10 mV for at least 60% of the UI within the eye opening." The 82580 might marginally fail this requirement.

**Implication:** IEEE conformance is marginal.

The Tx distortion is less than 10 mV during the critical time when the signal is actually sampled therefore no impact on system performance is observed with the 82580 due to this marginality.

**Workaround:** None



Status: A1 NoFix

## 17. NC-SI: Get NC-SI Pass-through Statistics Response Format

**Problem:** The NC-SI Specification, version 1.0.0a defines the Pass-through Tx Packets counter contained in the Get NC-SI Pass-through Statistics Response Packet to be an 8-byte field. The 82580 provides this counter as a 4-byte field.

**Implication:** A BMC that uses the Get NC-SI Pass-through Statistics command and expects the response format as described in the NC-SI Specification will not parse the response as intended by the 82580 and will obtain inaccurate statistics.

**Workaround:** The BMC can account for the different format provided by the 82580 and parse the response accordingly.

Status: A1 NoFix

## 18. PCIe Reset Causes FW Reset When Ports Are Disabled

**Problem:** If one or more of the ports are disabled by strapping (asserting LANx\_DIS\_N) or from the EEPROM (by setting the LAN\_DIS bit offset 0x20, bit 11), the firmware is reset following a PCIe reset. This applies to the 82580DB (dual-port) device even if neither port is explicitly disabled.

**Implication:** The manageability configuration is cleared by the PCIe reset and therefore any active session is disconnected.

On some of the ports the PHY is not configured correctly following the negation of the PCIe reset until the driver is loaded and resets the PHY. An incorrectly configured PHY could cause link issues and prevent WoL and/or manageability pass-through from working during this period of time.

**Workaround:** The Management Controller should re-run the initialization following PCIe reset to restore the configuration.

No workaround is available for the PHY configuration issues; the EEPROM should be updated to avoid this issue.

Status: Fixed in EEPROM

Fixed in EEPROM version 3.29. Contact your Intel representative to obtain updated EEPROM images.

## 1.5.5 Software Clarifications

Applies to Intel drivers, EEPROM loads.

### 1. While In TCP Segmentation Offload, Each Buffer is Limited to 64 KB

**Clarification:** The 82580 supports 256 KB TCP packets; however, each buffer is limited to 64 KB since the data length field in the transmit descriptor is only 16 bits. This restriction increases driver implementation complexity if the operating system passes down a scatter/gather element greater than 64KB in length. This can be avoided by limiting the offload size to 64 KB.

Investigation has concluded that the increase in data transfer size does not provide any noticeable improvements in LAN performance. As a result, Intel network software drivers limit the data transfer size in all drivers to 64 KB.



Please note that Linux operating systems only support 64 KB data transfers.

For further details about how Intel network software drivers address this issue, refer to Technical Advisory TA-191.

## 2. EEPROM Checksum Not Set for LAN1, 2, 3

**Clarification:** Intel provides tools to change EEPROM content: EEUPDATE, LANCONF, and CELO. Prior to SW Release 15.7, these tools changed EEPROM content but did not update or program the EEPROM checksums for LAN1, LAN2, and LAN3. More recent Intel EEPROM tools releases (Release 15.7 and later) fix this issue; they update and set EEPROM checksums for LAN 0,1,2,3.

The more recent tools also set word 0x3 (bit 15) in the EEPROM. This setting indicates that all four EEPROM checksums are valid. If bit 15 is not set, only the LAN 0 checksum is valid.

**Note:** Word 0x3 (bit 15) in the EEPROM was previously RESERVED in the documentation. The bit is now used for the above purpose and is no longer RESERVED.

## 3. Serial Interfaces Programmed By Bit Banging

**Clarification:** When bit-banging on a serial interface (such as SPI, I<sup>2</sup>C, or MDIO), it is often necessary to perform consecutive register writes with a minimum delay between them. However, simply inserting a software delay between the writes can be unreliable due to hardware delays on the CPU and PCIe interfaces. The delay at the final hardware interface might be less than intended if the first write is delayed by hardware more than the second write. To prevent such problems, a register read should be inserted between the first register write and the software delay, i.e. "write", "read", "software delay", "write".





**NOTE:**      *This page intentionally left blank.*