

PACKAGING PROCESS SHEET

STANDARD PACKAGING PROCESS FOR CATALOG NBR 130191 00 CURRENT

UM PC ORG CODE 0G30 PROD CDE 3060

SUPPLIER MFG DATE 06/09/03

COUNTRY CODE US

TRADEMARK NM SOLISTRAND

STANDARD QUANTITY - 1000

DESCRIPTION WIRE CONNECTOR

STANDARD LEVEL - 200

PRODUCT DESC TERM, SOLIS R 12-10 5MM

MARKING UL CSA

PRODUCT & APPROVAL LAST CHANGED: 05/06/10 REASON FOR CHG UPC ADD

SPEC/PKG CODE INFO LAST CHANGED: 06/09/03 PACKAGING REV Z

SPEC. TO REF. REV. DESCRIPTION

=====	=====	=====
102-00060	K	CAGE Codes and Date Coding
107-00253	J	Cartons, Standard Packing Methods f or
122-01022	B	Weigh Counting, Procedure For, AC/B Group, North and South

UNIT PACKAGING DESCRIBED BELOW:

PLC 200
LAST CHANGED: 06/08/09

PACKAGE QUANTITY	1000			
INSTRUCTION	LBL FORMATS	COMP PN DATA		
SHEET REQD.	REQUIRED	USED FOR LBL		
=====	=====	=====		
408-02049	999287-1			
PKG MTL	PKG MTL	PKG MTL	PKG MTL	
REQUIRED	DESCRIPTION	QUANTITY	U/M	
=====	=====	=====	=====	=====
12510-2	CARTON, FOLDING	1.0000000	PC	
999585-1	LABEL STOCK	1.0000000	PC	

OPERATION DESCRIPTION

LOAD PARTS AND INSTRUCTION SHEET IN UNIT BOX AND ATTACH LABEL.

ALT LBL FMT 995151-1 AND LBL STOCK 10411-2 CAN BE USED INSTEAD OF LBL FMT 999287-1 AND LBL STOCK 999585-1

SHIPPER PACKAGING DESCRIBED BELOW:

PLC 400
LAST CHANGED: 10/28/03

PACKAGE QUANTITY	10000			
INSTRUCTION	LBL FORMATS	COMP PN DATA		
SHEET REQD.	REQUIRED	USED FOR LBL		
=====	=====	=====		
	999102-1			
PKG MTL	PKG MTL	PKG MTL	PKG MTL	
REQUIRED	DESCRIPTION	QUANTITY	U/M	
=====	=====	=====	=====	=====
12110	BOX, CORR, FOL	1.0000000	PC	
995575-1	TAPE, PACKAGING, TRANSPARENT	1.0000000	MR	
999264-1	LABEL STOCK	1.0000000	PC	

PACKAGING PROCESS SHEET

STANDARD PACKAGING PROCESS FOR CATALOG NBR 130191 00 CURRENT

UM PC ORG CODE 0G30 PROD CDE 3060

SUPPLIER MFG DATE 06/09/03

COUNTRY CODE US

TRADEMARK NM SOLISTRAND

STANDARD QUANTITY - 1000

DESCRIPTION WIRE CONNECTOR

STANDARD LEVEL - 200

PRODUCT DESC TERM, SOLIS R 12-10 5MM

SHIPPER PACKAGING DESCRIBED BELOW:

PLC 400

LAST CHANGED: 10/28/03

PACKAGE QUANTITY 10000

OPERATION DESCRIPTION

=====

- SET UP BOX.
- TAPE BOTTOM OF BOX.
- PACK CARTONS INTO BOX.
- TAPE BOX CLOSED.
- LABEL BOX.