

SQUIB CABLE ASSY

1. PURPOSE 目的

Define the packaging specification and packaging method of SQUIB CABLE ASSY.

订定 SQUIB CABLE ASSY 产品之包装规格及包装方式。

2. APPLICABLE PRODUCT 适用范围

Product Part Number	Description
2050661-1/2	SQUIB CABLE ASSY
2137631-1/2/3	SQUIB CABLE ASSY
2209021-1/2	SQUIB CABLE ASSY C303
2137972-1/2	SQUIB CABLE ASSY C303

3. PACKAGING MATERIAL 包装材料

Package	Part No.	Description	Size(mm)	Usage	
				2050661-1/2 2137972-1/2 2137631-1/2/3	2209021-1/2
INNER	1533282-4	PE BAG	305x381	1/10	1/10
	623865-4	INNER LABEL	102X51	1/10	1/10
MIDDLE	-	-	-	-	-
OUTER	110455-2	BUBBLE PACK	349X304X12	2/100	6/100
	12120-1	SHIPPING BOX	349X298X146	1/100	-
	115216	SHIPPING BOX	349X298X240	-	1/100
	623865-5	OUTER LABEL	165X102	1/100	1/100

	Inner	Middle	Outer
LABEL	623865-4	-	623865-5
SEALING	Heat seal	-	Tape

4. PACKAGING QUANTITY 包装数量

	Inner	Middle	Outer
QTY	10 pcs/ bag	-	100 pcs/shipping box

DR
Sam Wu

CHK
Brent Huang

APVD
Ansin Yang

5. PACKING METHOD 包装方法

5.1. Coil individual cable, tie it with wire, tie 10 cables to one bundle, then put it into bag and heat seal it.

将每一条产品单独盘绕好（根据袋子大小）后用扎带扎好，然后将10条扎好的产品用扎带扎成一捆，再放入袋子并热封其开口。

5.2. Set up a box and secure bottom flaps with tape.

折叠好一个外箱，并用胶带封好箱底。

5.3. Place one piece of bubble pack, bubble facing down into the bottom of box.

在箱底放入一块气泡垫，气泡面朝下。

注：其中2209021-1/2需放3块气泡垫。

5.4. Place 10 bags of production into box.

将10袋产品整齐放入外箱中。

5.5. Place one piece of bubble pack on the top of cables, bubble facing up.

在CABLE 的上面放一块气泡垫，气泡面朝上。

注：其中2209021-1/2需放3块气泡垫。

5.6. Seal the box with tape. And place product identification label in "product id" marked on box.

用胶带封箱，在箱外印有“PRODUCT ID”标识处贴上外标签。