

PLEASE CHECK WWW.MOLEX.COM FOR LATEST PART INFORMATION

Part Number: [1301790328](#)
Status: **Active**
Overview: [Aero-Motive Repair Parts and Accessories](#)
Description: Secondary Support Chain for EB, F, FLRC and 1515T Balancers

Documents:

[RoHS Certificate of Compliance \(PDF\)](#)

General

Product Family	Tool Supports
Series	130179
Cable Length	N/A
Duty	N/A
Overview	Aero-Motive Repair Parts and Accessories
Product Name	Aero-Motive
Type	Replacement Part, Secondary Support
UPC	78678884922

Physical

Cable Diameter	N/A
Cable Movement	N/A
Drum Lock	None
Mounting Style	N/A
Packaging Type	Carton
Travel Distance	N/A
Weight Range	N/A
Wire/Cable Type	N/A

Material Info

Engineering Number	SSPEC
--------------------	-------



EU ELV

Not Relevant

EU RoHS

Not Reviewed

REACH SVHC

Not Reviewed

Halogen-Free

Status

Not Reviewed

For more information, please visit [Contact US](#)

China ROHS

Not Reviewed

ELV

Not Relevant

RoHS Phthalates

Not Reviewed

Search Parts in this Series

[130179 Series](#)